ate: User:

Tuesday, 06/05/2008 8:54:59 AM

Julie Lecocq

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 39067A

**Estimate Number** 

: 10122

P.O. Number

This Issue

Previous Run

Comment

: 06/05/2008

Prsht Rev. First Issue

: NC

: // : 36578A

S.O. No. :

Type

: LARGE FAB ASSY

Part Number

: D3043041

: A119 STEP WELDMENT LH

**Drawing Number** 

**Drawing Name** 

: D3043 REV A

**Project Number** 

: N/A

**Drawing Revision** 

Material **Due Date** 

: 30/05/2008

Qty:

5 Um:

Each

Written By

Checked & Approved By

: Est Rev :A

New Issue

Total:

05-11-01 JLM

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

2.0

D2622120C

LARGE FAB 1

1.0000 Each(s)/Unit Comment: Qty.:

5.0000 Each(s)

Step Extrusion

Pick:D2622-120 extrusion

Batch: 337754

LARGE FABRICATION RESOURCE 1

Comment: LARGE FABRICATION RESOURCE 1

1-Cut D2622-120 extrusion to 120.00" long as per Dwg D3043 using cutting table setup DT8185-G

2-Deburr and bevel ends for welding QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

4.0

3.0

D2734

Step End Plate



2.0000 Each(s)/Unit Total: Comment: Qty.:

10.0000 Each(s)



2 D2734

Qty Part Number Description Batch

5.0

D30401

End Cap

336520

Mounting Lug

Comment: Qty.: 2.0000 Each(s)/Unit

Total:

10.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3040-1 Mounting Lug **B33896** 

Page 1

# **Dart Aerospace Ltd**

W/O:		WORK ORDER CH	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr  Approval QC Inspector		
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	 <b>∆</b> :	Date:		

QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Decemption of NC		Corrective Action Section B						
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
		*								

Tuesday, 06/05/2008 8:54:59 AM Date: User: 3 Julie Lecocq **Process Sheet** Drawing Name: A119 STEP WELDMENT LH Customer: CU-DAR001 Dart Helicopters Services Part Number: D3043041 Job Number: 39067A Job Number: Seq. #: **Description: Machine Or Operation:** Mounting Lug 6.0 D30403 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Comment: Qty.: Qty Part Number Description Batch 2 D3040-3 Mounting Lug 335976 LARGE FAB 1 ARGE FABRICATION RESOURCE 1 7.0 Comment: LARGE FABRICATION RESOURCE 1 1-Weld 1 End Cap & Mounting Lugs as per QSI 004 & Dwg D3043 Using DT8802 AR AL ROD Batch: <u>m/06834</u> m/07678 2-Grind Fwd End Cap weld flush VISUAL WELDING INSPECTION 8.0 QC9 Comment: VISUAL WELDING INSPECTION INSPECT WORK TO CURRENT STEP 9.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE #1 10.0 HAND FINISHING Comment: HAND FINISHING RESOURCE #1 1-Chemical Conversion Coat as per QSI 005 4.1 11.0 LARGE FAB 1 LARGE FABRICATION RESOURCE Comment: LARGE FABRICATION RESOURCE 1 1-1-Weld 1 End Cap as per QSI 004 & Dwg D3043 AR AL ROD Batch: MIDIO 834 2-Inspect for foreign object as per QSI 024 3-Grind Fwd End Cap weld flush Page 2

# Dart Aerospace Ltd

W/O:		WORK ORDER C	WORK ORDER CHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		, ·	·				
Dant Na	_	DAD #					L

Part No: _	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
			QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B			Approval Chief Eng	Amment		
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date		- Verification Section C	Approval QC Inspecto				
					:					
						·				

Tuesday, 06/05/2008 8:54:59 AM Date: User: " Julie Lecocq **Process Sheet** Drawing Name: A119 STEP WELDMENT LH Customer: CU-DAR001 Dart Helicopters Services Part Number: D3043041 Job Number: 39067A Job Number: Seq. #: Description: **Machine Or Operation:** VISUAL WELDING INSPECTION 12.0 Comment: VISUAL INSPECT WORK TO CURRENT STEP 13.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE #1 14.0 HAND FINISHING Comment: HAND FINISHING RESOURCE #1 1-Touch up Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION 15.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION Inspect alodine POWDER COATING POWDER COATING 16.0 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 START TIME: OVEN TEMPERATURE: FINISH TIME: HAND FINISHING RESOURCE # 17.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 1-Wing Walk as per Dwg D3043 and QSI 005 4.4 INSPECT POWDER CO 18.0 QC3

ÓN /

(5

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

рап Ае	rospace	e Lta							
W/O:			WC	RK ORDER CHAN	IGES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	es No DG	A:	_ Date: _	<del></del>
				•	QA	: N/C Close	ed:	_ Date: _	
NCR:			WORK ORD	R NON-CONFORI	MANCE (N	CR)			
DATE	CTED	Description of NC			ection B	Verif	ication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	n Sig Da		tion C	Chief Eng	QC Inspector
		4							
	1		1		1	I		i .	i

Date:

Tuesday, 06/05/2008 8:54:59 AM

User: "

Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: A119 STEP WELDMENT LH

Job Number: 39067A

Part Number: D3043041

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

19.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and S Location:



20.0



CTION/W/O RELEASE Comment: FINAL IN

Job Completion



## **Dart Aerospace Ltd**

W/O:			WC	ORK ORDER CHANGES	3				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
:									
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
					QA: N	/C Close	d:	Date: _	
NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
		•							
							<del></del>		





DESIG	n UP	DRAWN BY	DART AEROSPACE U	JSA, INC.
CHECK	(EO A	APPROVED	drawing no. D3043	REV. A SHEET 1 OF 2
DATE			TITLE	SCALE
 01.0	06.28		A119 STEP WELDMENT	NTS
Α		01.06.28	NEW ISSUE	

### PARTS LIST:

Qty -041	Qty -043	Part Number	Description
Х		D3043-041	STEP WELDMENT, LH
	Х	D3043-042	STEP WELDMENT, RH
1	1	D2622-120	STEP EXTRUSION
2	2	D3040-1	MOUNTING LUG
2	2	D3040-3	MOUNTING LUG
2	2	D2734	ENDPLATE

### NOTES:

- 1) MANUFACTURE FROM D2622-120 EXTRUSION
- 2) WELD PER DART QSI 004. ALL WELDS SHOULD BE 100% VISUALLY INSPECTED BY A QUALIFIED INSPECTOR PER DART QSI 004
- 3) FINISH: ACID ETCH & ALODINE ASSEMBLY PER DART QSI 005 4.1
  POWDER COAT WHITE (REF 4.3.5.1) PER DART QSI 005 4.3
  BLACK ANTI-SKID PAINT TOP SURFACE OF STEP TO BOTTOM OF TOP
  RADIUS PER DART QSI 005 4.4
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER


SHOP COPY





Copyright @ 2001 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.









VIEW A-A: D3043-042 RH STEP WELDMENT

Copyright © 2001 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.